


[Working Methods] When different LED bar connectorOnly

When different LED bar connector, direct soldering working guide.

1. When different LED Bar connector



3-1. Tester use pattern check(Not open)




4-1. If not open case, could you soldering.



2. Cutting the in cable for connector.



3-2. Tester use pattern check(open)



4-2. If not open case, could you soldering.

